

Lathe Safety Check

**Do Not Turn if Tired,
Upset, Sick or Tippy**

Use Safety Glasses & Face Mask

**Wear Short Sleeves, No Jewelry,
Comfortable Shoes; Tie-up Hair**

Sharpen Tools

**Remove Shavings and Clutter,
Eliminate Distractions**

**Is Blank Sound and Securely
Mounted? (both ends)**

**Check Locks on Tool Rest,
Banjo, Tailstock, etc.**

Rotate Work by Hand First

**Begin at Low Speed,
Listen while Turning**

Turn Lathe Off for Adjustments

**Remove Tool Rest and
Use Dust Mask while Sanding**

Lathe Safety Check

**Do Not Turn if Tired,
Upset, Sick or Tippy**

Use Safety Glasses & Face Mask

**Wear Short Sleeves, No Jewelry,
Comfortable Shoes; Tie-up Hair**

Sharpen Tools

**Remove Shavings and Clutter,
Eliminate Distractions**

**Is Blank Sound and Securely
Mounted? (both ends)**

**Check Locks on Tool Rest,
Banjo, Tailstock, etc.**

Rotate Work by Hand First

**Begin at Low Speed,
Listen while Turning**

Turn Lathe Off for Adjustments

**Remove Tool Rest and
Use Dust Mask while Sanding**

Lathe Safety Check

**Do Not Turn if Tired,
Upset, Sick or Tippy**

Use Safety Glasses & Face Mask

**Wear Short Sleeves, No Jewelry,
Comfortable Shoes; Tie-up Hair**

Sharpen Tools

**Remove Shavings and Clutter,
Eliminate Distractions**

**Is Blank Sound and Securely
Mounted? (both ends)**

**Check Locks on Tool Rest,
Banjo, Tailstock, etc.**

Rotate Work by Hand First

**Begin at Low Speed,
Listen while Turning**

Turn Lathe Off for Adjustments

**Remove Tool Rest and
Use Dust Mask while Sanding**